

# Paintless Dent Removal (PDR)

**Nissan Altima**  
(aluminum trunk)



# Paintless Dent Removal (PDR)

2004


Honda Element



# Paintless Dent Removal (PDR)

**Volvo**

Sharp Crease



# Paintless Dent Removal (PDR)

Camry



# Paintless Dent Removal (PDR)

Lexus



# Paintless Dent Removal (PDR)

## Camry

Plastic Bumper Repair  
"No" Painting



# Paintless Dent Removal (PDR)

## Nissan Murano

Plastic Bumper Repair  
Scuff Removal  
"No" Painting



# Paintless Dent Removal (PDR)

**1999 Buick**


Plastic Bumper Repair  
Scuff Removal  
"No" Painting



# Paintless Dent Removal (PDR)

## Camry

Plastic Bumper Repair  
"No" Painting



# Paintless Dent Removal (PDR)

Honda  
Accord



# Paintless Dent Removal (PDR)

**Honda  
Pilot**



# Paintless Dent Removal (PDR)

## Prius


### PDR and Clean-Up



# Paintless Dent Removal (PDR)

**Honda Accord**

**Deep Dent and Crease**



# Paintless Dent Removal (PDR)

2008

Sienna Van

Soccer Ball Dent



# Paintless Dent Removal (PDR)

Volkswagen



# Paintless Dent Removal (PDR)



Nissan



# Headlight Restoration



Pontiac



# Headlight Restoration

1998

Buick LaSabre



# Headlight Restoration



Volkswagon  
Jetta



# PDR, Bumper Repair and Paint



**Honda Pilot**  
PDR and Paint Repair



# PDR, Bumper Repair and Paint



**Honda Pilot**  
PDR and Paint Repair



# Bumper Repair and Paint



**Mazda 3**

**Plastic Bumper Had Deep Scrapes**